

104





Fig. 1




Fig. 2




FIG. 3

400

Amplifiers 356

	Amp 356a	Amp 356b	Amp 356c	Amp 356d	Amp 356e	Amp 356f	Amp 356g	Amp 356h	Amp 356i	Amp 356j
VCO 318a	ON	OFF	OFF	OFF	ON	OFF	OFF	ON	ON	OFF
VCO 318b	OFF	ON	OFF	OFF	ON	OFF	OFF	ON	ON	OFF
VCO 318c	OFF	OFF	ON	OFF	OFF	ON	ON	ON	ON	OFF
VCO 318d	OFF	OFF	OFF	ON	OFF	ON	ON	OFF	OFF	ON

VCO 318

Fig. 4






FIG. 5A



On the 20th of May, 1863, the 10th Mass. Regt. was mustered out of the service at Boston, and the 10th Mass. Regt. was mustered in at Boston, on the 21st of May, 1863.

334






Fig. 7






Fig. 8

FIG. 9



900

Fig.10



8022




FIG. 11




Fig. 12

loop




FIG.13




FIG. 14




Fig. 15

1600
↓




FIG. 16




Fig. 17






FIG. 18








Fig. 21




Fig. 22

1928




Fig. 23.

